

CLASSIFIED MESSAGE

ROUTING

DATE 1201Z 21 JAN 63

S E C R E T

1	2
2	5
3	6

25X1A

TO DIRECTOR

FROM [REDACTED]

ACTION OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

INFO S/C (17)

TOR: 0003Z 22 JAN 63

25X1A

IN 63263

25X1A

25X1A

25X1A PRIORITY

INFO

CIT

25X1A

25X1A

25X1A

25X1A

PASS TO

20

25X1A

1. G-3213/5675/ [REDACTED]

2. 9R/0-11-6000/189-10-9-6-2/9L/0-11-6000/188-9-12-5-2

3. D-19/4/75 DEGREES/HTA/2

4. 2.2

5. MEDIUM TO HEAVY/MEDIUM TO HIGH/GOOD TO POOR/SEE PARA 6

6. TAKE RECEIVED AT 1423Z IN COVERED STEEL BOXES. CONDITION GOOD.

DATA CHAMBERS ON BOTH 9R AND 9L INTERMITTENTLY OUT OF FOCUS BEGINNING AT EXPOSURE NR 1821. BOTH 9L AND 9R FRAMES INTERMITTENTLY OUT OF FOCUS FROM INNER EDGE AND EXTENDING INTO APPROXIMATE CENTER OF 9 INCH FRAME WITH FOCUS BECOMING BETTER AS IT APPROACHES OUTSIDE CENTER OF FRAME. APPARENT CAUSE, VACUUM FAILURE. FILM CREASE DUE TO FOLD IN PROCESSOR DRY BOX (HTA/2), FROM FRAME NR 931 TO 938, 9L. SMALL TEARS FRAME NRS 269, 271, 273, 9L DUE TO SP 10/70 PRINTER MALFUNCTION. DESENSITIZED SPOTS REPORTED IN PREVIOUS

S E C R E T

25X1A

Approved For Release 2002/10/31 : CIA-RDP89B00569R000200140012-5

25X1A

S E C R E T

[REDACTED] (IN 63268)

PAGE TWO

[REDACTED] REPORTS NO LONGER IN EVIDENCE. METERING GOOD.

7. NOT ACCOMPLISHED

8. TAKE TO BE FORWARDED BY COURIER APPROX 1900 LOCAL, 22 JAN 1963.

END OF MESSAGE

S E C R E T

Approved For Release 2002/10/31 : CIA-RDP89B00569R000200140012-5